

# *Leadscrew and Backlash Strapping*

## *For "B" Mills (Interface Board)*

- Notes: 1. Strap Sign Bit to move axis shorter.  
2. Values shown are for a 13.1 " move.

